

CE1205 CONSTRUCTION MATERIALS

WEEK 4

Chapter 3 FATIGUE, CREEP AND CORROSION 'METAL FAILURE'

PowerPoint[®] Slides by Salmaliza Salleh

Chapter Overview

- Chapter 3 exposed you with the different types of metal failures.
- You learned about what are the factors that cause the failures.
- You also learned how to control these failures.

Learning Objectives

 To expose the students to different types of metal failure such as fatigue, creep and corrosion, what are the factors that cause these failures and how to control them.

Learning Outcomes

 At the end of the lesson, students should be able to identify and explain the types of metal failures, the contributing factors and controlling method.

INTRODUCTION TO FATIGUE

Definition: The effect on metal of <u>repeated</u> cycles of

 The insidious feature of fatigue failure is that there is obvious warning, a crack forms without appreciable deformation of structure making it difficult to detect the presence of growing cracks.

• <u>Fracture</u> usually start from small nicks or scratches or fillets which cause a localised concentration of stress.

 Failure can be influenced by a number of factors including size, shape and design of the component, condition of the surface or operating environment.

- Fatigue results in a <u>bittle</u> appearing fracture, with no gross deformation at the fracture.
- A fatigue failure can usually be recognized from the appearance of the fracture surface which shows a smooth region, due to the rubbing action as the crack propagated through the section, and a rough region, where the member has failed in a ductile manner when the cross section was no longer able to carry the load.





- Three basic factors are necessary to cause fatigue failure. These are:
 - maximum <u>tensile</u> stress of sufficiently high value,
 - 2. large enough variation or <u>flucti</u> in the applied stress, and
 - 3. sufficiently large number of <u>ryeles</u> of the applied stress.

- In addition, there are a host of other variables, such as:
 - stress concentration,
 - corosion
 - temperature
 - overload,
 - metallurgical structure,
 - residual stresses, and
 - combined stresses, which tend to alter the conditions for fatigue.

METALLURGY

The science that deals with procedures used in extracting metals from their ores, purifying and alloying metals, and creating useful objects from metals.

The study of metals and their properties in bulk and at the atomic level.

Residual Stresses

- Definition: Stresses that remain in material or body without application of an external load (applied force, displacement of thermal gradient).
- Origin: Usually originates during <u>manufacturing</u> and processing of materials due to *heterogeneous plastic deformations, thermal contractions and phase transformations

*Heterogeneous: Consisting of dissimilar elements or parts; not homogeneous.

Fatigue Design Guideline (minimize stress concentrations)

- 1. Consider <u>all types</u> stresses, including stress concentrations, rather than to nominal average stresses.
- Visualize load <u>distribution</u> from one part or section to another and the distortions that occur during loading to locate points of high stress
- Avoid adding or attaching <u>more</u> brackets, fittings, handles, steps, bosses, grooves, and openings at locations of high stress
- 4. Use <u>gradual changes</u> changes in section and symmetry of design to reduce secondary flexure

© LMS SEGi education group 12

- 5. Consider location and <u>types</u> of joints (frequent cause of fatigue problems)
- 6. Use <u>double</u> shear joints when possible
- Do not use <u>rivets</u> for carrying repeated tensile loads (bolts superior)
- 8. Avoid open and loosely filled <u>holes</u>
- 9. Consider <u>standard</u> methods, specify strict requirements when needed
- Choose proper surface <u>arushes</u> but not overly severe (rivet holes, welds, openings etc. may be larger drivers)



MDS Counteres

AAAD Shar in

- 1. Provide suitable protection against corrosion
- 12. Avoid <u>metal piahrg plating with widely different</u> properties than underlying material
- ^{13.} Consider <u>pre-stressery</u> when feasible
- 14. Consider maintenance, to include <u>inspection</u> and protection against corrosion, wear, abuse, overheating, and repeated overloading
- Avoid use of structures at critical or fundamental frequency of individual parts or of the structure as a <u>whole (induces many cycles of relatively high stress)</u>
- 6. Consider <u>temperature</u> effects

INTRODUCTION TO CORROSION





 Corrosion is <u>chemically</u> induced damage to a material that results in deterioration of the material and its properties.

WHY METALS CORRODE?

Metals corrode because we use them in environments where they are chemically unstable .Only copper and the precious metals (gold, silver, platinum, etc.) are found in nature in their metallic state. All other metals, to include iron-the metal most commonly used-are processed from minerals or ores into metals which are inherently unstable in their environments.

Design considerations Factors that can influence corrosion:

- Environment
 - Chemical
 - Natural
 - Storage, transit

Stress

- Residual stress from fabrication
- Static, variable and alternating operating stresses

Shape

•

- Joints and flanges
- Crevices and deposits
- Trapped and contained liquid

Compatibility

- Metals with metals
- Metals with other materials
- Quality control of materials

Movement

- Flowing fluids
- Parts moving in fluids
- Two- and three-phase flow
- Entrained solids
- · Vibration and pulsing

Temperature

•

- Oxidation, scales and tarnishes
- Heat-transfer effects
- Molten deposits
- Condensation and dewpoints

Control

- Surface cleaning and preparation
- Coatings
- Cathodic protection
- Inhibitors
- Inspection
- Planned maintenance

- Several factors should be considered during a failure analysis to determine the affect corrosion played in a failure.
 Examples are listed below:
 - Type of corrosion
 - Corrosion rate
 - The extent of the corrosion
 - Interaction between corrosion and other failure mechanisms

COMMON TYPES OF CORROSION

Uniform or General Corrosion

- The metal loss is uniform from the surface.
- The reaction starts at the surface and proceeds uniformly.
- Often combined with high-velocity fluid erosion, with or without abrasives.

<u>Pitting</u> Corrosion

- The metal loss is randomly located on the metal surface.
- The basis metal is eaten away and perforated in places in the manuel of • holes, the rest of the surface being affected only slightly or not at all.
- Often combined with stagnant fluid or in areas with low fluid velocity.

Galvanic Corrosion

- Increased corrosion in crevices or cracks or at contact surfaces between two metal articles.
- Occurs when two metals with different electrode potential is connected • in a corrosive electrolytic environment.
- The anodic metal develops deep pits and groves in the surface.



*Crevice Corrosion

- Occurs at places with gaskets, bolts and lap joints where crevice exists.
- · Crevice corrosion creates pits similar to pitting corrosion.

Concentration Cell Corrosion

- Occurs where the surface is <u>exposed</u> to an electrolytic environment where the concentration of the corrosive fluid or the dissolved oxygen varies.
- Often combined with stagnant fluid or in areas with low fluid velocity.

Graphitic Corrosion

- · Cast iron loosing iron in salt water or acids.
- Leaves the graphite in place, resulting in a soft weak metal.

*Crevice: a long narrow opening [syn: <u>crack</u>*Crevice: a long narrow opening [syn: crack, <u>cleft</u>*Crevice: a long narrow opening [syn: crack, cleft, <u>fissure</u>*Crevice: a long narrow opening [syn: crack, cleft_fissure_scissure]





Electrochemical corrosion

Four conditions must exist before electrochemical corrosion can proceed:

(1) there must be something that corrodes , the metal _____ where the oxydation reaction takes place

(2) there must be a _____, where the reduction reaction takes place

(4) there must be a ______ to carry the flow of electrons from the anode to the cathode.



Current Flow (Ionic Conduction)

E.g. Electrochemical corrosion of iron due to contact with water



 This conductor is usually in the form of metal-to-metal contact such as in bolted or riveted joints.

The elimination of any one of the four conditions will <u>remote</u> the conditions that causes corrosion. An unbroken (perfect) ______ on the surface of the metal will prevent the electrolyte from connecting the cathode and anode so the current cannot flow.

Therefore, no corrosion will occur as long as the coating is unbroken.

 Corrosion is a normal, natural process. Corrosion can seldom be totally prevented, but it can be ______ or controlled by proper choice of material, design, coatings, and occasionally by changing the environment.

 Various types of metallic and nonmetallic coatings are regularly used to protect metal parts from corrosion.

CORROSION CONTROL

- There are a number of means of controlling corrosion. The choice of a means of corrosion control depends on
 - economics,
 - safety requirements, and
 - a number of technical considerations.
- Failure to control corrosion can lead to:
 - Increase costs
 - reduced <u>safety</u>
 - <u>Negative</u> environmental impact

CORROSION CONTROL

- Protective
 - Can be metallic, such as the galvanized steel or they can be applied as a liquid "_____."

protection,

 Cathodic protection is an electrical means of corrosion control. It can be applied using sacrificial (galvanic) anodes.

Corrosion inhibitors

 Corrosion inhibitors are ______ that are added to controlled environments to reduce the corrosivity of these environments.

INTRODUCTION TO CREEP

- When a material is subjected to a stress that is greater than or equal to its yield stress, the material deforms *plastically*. When the stress is below this level, then in principle it should only deform elastically.
- However, provided the ______ is relatively ______, plastic deformation can occur even when the stress is lower than the yield stress. This deformation is time-dependent and is known as creep.

CREEP OF METALS

- High temperature progressive deformation of a material at constant stress is called creep. High temperature is a relative term that is dependent on the materials being evaluated.
- Creep occurs under load at high temperature. Boilers, gas turbine engines, and ovens are some of the systems that have components that experience creep.

 For a low melting point metal like lead, creep becomes significant at about 27⁰C, i.e. on a hot day. This may cause drainage piping made from lead to sag between its supports or lead plates to creep in a battery.

 For a high melting point metal like tungsten, temperatures above 1500°C would be needed to produce creep.

CREEP CURVE

• A typical creep curve is shown below:



strength.

- II. Greater atomic and dislocation mobility, assisting dislocation climb and diffusion.
- III. New _____ mechanisms, such as new slip systems or grain boundary sliding.
- v. Recrystallisation and grain growth.
- v. Age hardened alloys will _____ by particle coarsening and lose strength.
 - Oxidation and intergranular penetration.

L

REFERENCES

- <u>http://www.materialsengineer.com/CA-corrosion.</u>
 <u>htm</u>
- http://www.tis-gdv.de/tis_e/misc/korro.htm
- http://www.engineeringtoolbox.com/corrosion-d_ 986.html
- http://www.tech.plym.ac.uk/sme/mats340/cpintro .pdf