Repaired units



FX1800 SHO



The reason of occurrence of defects - transport damages















Big damage of hull

Damage of painting surface (deep scratches)


VX1100.

Damages inside package.

Result of moving (Insufficiently strong fastening of unit in packing).
Through damage of the case and damage of the painted surface.
The same damages are possible in a current of normal use (on water)



Other small damages of the top part of the hull. Paint scratch and cracks. All damages can be repaired.



Equipment and tool





General equipment:

- Lifting equipment (electrical winch and spider (for boats)
- 1. Stands and support for convenient installation of a boat and WV for repair







Tool:

- 1. Protection
- 2. Lights
- 3. Ventilation













Tool and Materials




Air drill machine











(indicator for non polishing surface)



Tool for lamination procedure and polishing









First step of repair

Installation and preparation for repair







Need remove all parts, near repaired place (fender, transom plates, plastic parts).

Installation after repair.









Fixed unit on suitable position for normal repair and observing damaged places.


Strong fixation is important.

VX1100 is two stroke model. This installation type is acceptable.

Second step of repair

Damage area preparation for lamination.

Drilling, cutting and polishing area around damage.











Finally result

Add foam-plastic and prepare for lamination, cutting, polishing and gluing for good adhesive.
















Finally result

Third step of repair

Lamination process and polishing















Finally result

Time for waiting – 24 hours. After this time – polishing.

(Warning!!!! Procedure is Very dirty and dusty. Protection very important!!!)










Finally result

Information from FRP Repair Service Manual







- 1. Preparation for lamination
- 2. Lamination process with Roving cloth and Chopped strand mat.

Fourth step of repair

Preparation of surface for paint base. Putty and polishing. First time – glass putty

Two components putty. Sandpaper – (3M) P80. 3 – 5 steps



Preparation of surface for paint. Putty and polishing. Second time – soft putty Two components putty. Sandpaper – (3M) - P120 and final – P240 (for paint base)















Finally result

Fifth step of repair

Paint base and preparation for painting Important – need cover all hull (without painted area). Only on repaired place need put base.



After dry of base, Polishing. First time – polishing of repaired area (need equal surface with null).

Second time – need polish all surface of hull (matt surface for good adhesive of paint)









Sixth step of repair

Painting and polish.

Important: Good lights. Need cover area around painting area.

Good ventilation. Clean area (no dust). Need remove dust and fat

(don't use strong acid – you can damage old paint)



















Paint – TIKKURILA – TEMADUR 90. Water resistant (two components) paint.

Painting procedure – need practice and skill.

Sixth step of repair




This paint have good fluidity.

After painting, paint

create smooth surface.



After painting, before polish









Compound and tool for polishing.

FX upper side damage





Use soft putty




Painting and polish


Upper side and lower side WV repair

Different paint base for lower and upper side of WV's hull.

Different paint and surface processing. The Metallic paint is applied sometimes.

In this case the extra time and expenses for a choice of a paint and after-treatment is required.





YAMARIN Boats and YAMAHA WV Hull repair difference

YAMARIN Boat

Material – FRP

Color – gelcoat

Method of forming – Female mold with resin

Big size of Hull, big size of Female.

It is difficult to organize

automatic forming process of hull.

YAMAHA WV

Material – SMC

Color – Base and paint

Method of forming – Closed mold method

The method is specially necessary

for factory production of Hull

(with identical quality and
the identical geometrical sizes)

Competitor – BOMBARDIER

Material – FRP

Color – gelcoat

Method of forming – Female mold with resin.

Automatic forming with hand made.

Add gelcoat and FRP material with resin automatically on the female.

After that - manual handling (defoaming by rollers)