

# Neste Oyj Naantali Terminal Office



Terminal  
entrance and  
doorbell.



# Go to the office's service desk

## Requirements for the truck driver:

- A cleaning certificate with the following information:
  - Cleaned compartments
    - Cleaning method
    - Cleaning results
    - Previous product
  - Compartments dried yes/no
  - A document for a vacuum test
- The Driver must have an interpreter if he can not communicate in English.
- The driver must wear protective clothing at the loading area. Specifications mentioned below.
- If the driver has no protective clothing they can be borrowed from the terminal.
- After loading, return to the office and wait for the export documents.



You need protective clothing specifications:

- **Helmet with chin strap** (SFS-EN 39 or SFS-EN12492)
- **Goggles** (SFS-EN 166 and mechanical strength F)
- **Jacket (XS-3XL)** (SFS-EN-ISO 13688, SFS-EN-ISO 11612, SFS-EN-ISO 20471, SFS-EN 1149-5)
- **Trousers (50-62)** (SFS-EN-ISO 13688, SFS-EN-ISO 11612, SFS-EN-ISO 20471, SFS-EN 1149-5)
- **Protective gloves**
- **High leg safety shoes (37-45)** (SFS-EN-ISO 20345 S3 class)