



Психометр Августа

История

Был создан в 1828 году Эрнстом Фердинандом Августом




РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °С	
°С	1,0 1,5 2,0 2,5 3,0 3,5 4,0 4,5 5,0 5,5 6,0
20	90 85 81 76 71 67 63 58 54
21	90 85 81 77 72 68 64 59 55 51 47
22	91 85 82 77 73 69 64 61 56 52 48
23	91 86 82 78 74 70 65 62 58 54 50
24	91 87 83 78 74 70 66 62 58 55 51
25	91 87 83 79 75 71 67 63 60 56 52
26	92 88 84 80 76 72 69 65 61 58 54
27	92 88 84 80 77 73 69 66 62 59 55
28	92 88 84 81 77 73 70 66 63 60 56
29	92 88 85 81 78 74 71 67 64 61 57
30	92 89 85 82 78 75 71 68 65 61 58
31	93 89 85 82 78 75 72 69 65 62 59
32	93 89 86 82 79 76 72 69 66 63 60
33	93 89 86 83 79 76 73 70 67 64 61
34	90 86 83 80 76 73 70 67 64 61
35	90 86 83 80 77 74 71 68 65 62
36	90 87 83 80 77 74 71 68 66 63
37	90 87 84 81 78 75 72 69 66 63
38	90 87 84 81 78 75 72 70 67 64
39	90 87 84 81 78 76 73 70 67 64
40	91 88 85 82 79 76 73 70 68 65
РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °С	
°С	6,5 7,0 7,5 8,0 8,5 9,0 9,5 10,0 10,5 11,0 11,5

ОТНОСИТЕЛЬНАЯ ВЛАЖНОСТЬ, %

°С	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
1,0	44	41																			
1,5	46	42	39																		
2,0	48	44	40																		
2,5	49	45	42	38																	
3,0	51	49	44	41	39	35	32	29	26	23	20										
3,5	52	50	46	43	41	36	30	30	28	25	22										
4,0	53	51	47	44	42	38	35	32	29	27	24										
4,5	54	52	48	45	43	39	36	34	31	28	25										
5,0	55	53	49	46	44	41	38	35	32	30	27										
5,5	56	54	50	47	46	42	39	36	34	31	29										
6,0	57	55	51	48	47	43	40	38	35	33	30										
6,5	58	56	52	49	48	44	41	39	36	34	32										
7,0	59	57	53	50	49	45	43	40	38	35	33										
7,5	59	57	54	51	49	46	44	41	39	36	34										
8,0	60	58	55	52	50	47	45	42	40	38	35										
8,5	61	59	56	53	51	48	46	43	41	39	36										
9,0	61	59	56	54	52	49	47	44	42	40	37										
9,5	62	60	57	55	53	50	48	45	43	41	39										
10,0	63	61	58	55	53	51	48	46	44	42	39										

СКОРОСТЬ АСПИРАЦИИ от 0,5 до 1,0 м/с



Устройство

