



# Психометр Августа

# История

Был создан в 1828 году Эрнстом Фердинандом Августом




РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °С	
°С	1,0 1,5 2,0 2,5 3,0 3,5 4,0 4,5 5,0 5,5 6,0
20	90 85 81 76 71 67 63 58 54
21	90 85 81 77 72 68 64 59 55 51 47
22	91 85 82 77 73 69 64 61 56 52 48
23	91 86 82 78 74 70 65 62 58 54 50
24	91 87 83 78 74 70 66 62 58 55 51
25	91 87 83 79 75 71 67 63 60 56 52
26	92 88 84 80 76 72 69 65 61 58 54
27	92 88 84 80 77 73 69 66 62 59 55
28	92 88 84 81 77 73 70 66 63 60 56
29	92 88 85 81 78 74 71 67 64 61 57
30	92 89 85 82 78 75 71 68 65 61 58
31	93 89 85 82 78 75 72 69 65 62 59
32	93 89 86 82 79 76 72 69 66 63 60
33	93 89 86 83 79 76 73 70 67 64 61
34	90 86 83 80 76 73 70 67 64 61
35	90 86 83 80 77 74 71 68 65 62
36	90 87 83 80 77 74 71 68 66 63
37	90 87 84 81 78 75 72 69 66 63
38	90 87 84 81 78 75 72 70 67 64
39	90 87 84 81 78 76 73 70 67 64
40	91 88 85 82 79 76 73 70 68 65

РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °С	
°С	6,5 7,0 7,5 8,0 8,5 9,0 9,5 10,0 10,5 11,0 11,5
20	
21	44 41
23	46 42 39
24	48 44 40
25	49 45 42 38
26	51 49 44 41 39 35 32 29 26 23 20
27	52 50 46 43 41 36 30 28 25 22
28	53 51 47 44 42 38 35 32 29 27 24
29	54 52 48 45 43 39 36 34 31 28 25
30	55 53 49 46 44 41 38 35 32 30 27
31	56 54 50 47 46 42 39 36 34 31 29
32	57 55 51 48 47 43 40 38 35 33 30
33	58 56 52 49 48 44 41 39 36 34 32
34	59 57 53 50 49 45 43 40 38 35 33
35	59 57 54 51 49 46 44 41 39 36 34
36	60 58 55 52 50 47 45 42 40 38 35
37	61 59 56 53 51 48 46 43 41 39 36
38	61 59 56 54 52 49 47 44 42 40 37
39	62 60 57 55 53 50 48 45 43 41 39
40	63 61 58 55 53 51 48 46 44 42 39

СКОРОСТЬ АСПИРАЦИИ от 0,5 до 1,0 м/с



# Устройство

