



# Психометр Августа


# История

Был создан в 1828 году Эрнстом Фердинандом Августом



РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °С											
°С	1,0	1,5	2,0	2,5	3,0	3,5	4,0	4,5	5,0	5,5	6,0
20	90	85	81	76	71	67	63	58	54		
21	90	85	81	77	72	68	64	59	55	51	47
22	91	85	82	77	73	69	64	61	56	52	48
23	91	86	82	78	74	70	65	62	58	54	50
24	91	87	83	78	74	70	66	62	59	55	51
25	91	87	83	79	75	71	67	63	60	56	52
26	92	88	84	80	76	72	69	65	61	58	54
27	92	88	84	80	77	73	69	66	62	59	55
28	92	88	84	81	77	73	70	66	63	60	56
29	92	88	85	81	78	74	71	67	64	61	57
30	92	89	85	82	78	75	71	68	65	61	58
31	93	89	85	82	78	75	72	69	65	62	59
32	93	89	86	82	79	76	72	69	66	63	60
33	93	89	86	83	79	76	73	70	67	64	61
34	90	86	83	80	76	73	70	67	64	61	
35	90	86	83	80	77	74	71	68	65	62	
36	90	87	83	80	77	74	71	68	66	63	
37	90	87	84	81	78	75	72	69	66	63	
38	90	87	84	81	78	75	72	70	67	64	
39	90	87	84	81	78	76	73	70	67	64	
40	91	88	85	82	79	76	73	70	68	65	
РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °С											
°С	6,5	7,0	7,5	8,0	8,5	9,0	9,5	10,0	10,5	11,0	11,5
20											
21	44	41									
23	46	42	39								
24	48	44	40								
25	49	45	42	38							
26	51	49	44	41	39	35	32	29	26	23	20
27	52	50	46	43	41	36	30	30	28	25	22
28	53	51	47	44	42	38	35	32	29	27	24
29	54	52	48	45	43	39	36	34	31	28	25
30	55	53	49	46	44	41	38	35	32	30	27
31	56	54	50	47	46	42	39	36	34	31	29
32	57	55	51	48	47	43	40	38	35	33	30
33	58	56	52	49	48	44	41	39	36	34	32
34	59	57	53	50	49	45	43	40	38	35	33
35	59	57	54	51	49	46	44	41	39	36	34
36	60	58	55	52	50	47	45	42	40	38	35
37	61	59	56	53	51	48	46	43	41	39	36
38	61	59	56	54	52	49	47	44	42	40	37
39	62	60	57	55	53	50	48	45	43	41	39
40	63	61	58	55	53	51	48	46	44	42	39

СКОРОСТЬ АСПИРАЦИИ от 0,5 до 1,0 м/с



# Устройство

