

Lost Time Incident Report, Blumenau, 02/12/2020


What happened:

The employee was removing the chrome water roller from the offset unit. When removing the screws on one side and loosening on the other, the roller fell and when trying to hold it, he had one of the fingers of his hand pressed by the roller.

Immediate actions:

Develop procedure for assembling and disassembling the roller, training everyone involved in this activity.

Study the development of a support that prevents the roll from falling when releasing it.



Contact Info (Production Manager / Safety Contact):

Emerson Kieras emerson.kieras@all4labels.com.br

Tatiana Bertoldi tatiana.bertoldi@all4labels.com.br

Lost Time Incident Report, Gallin, 02/12/2020

Machine Operator Flexo

What happened:

The employee was cleaning the plates after the printing job was done, and when doing this, pressed the side of the plate (which is sharp) with his hands with too much pressure, and cut his finger. He was using safety gloves, but the wrong kind, with lower protection level.

Immediate actions:

Recheck all the gloves at the sites, making sure they are the correct type. Wrong type gloves can not be bought anymore.

Training from all the operators that execute this process.

Contact Info (Production Manager / Safety Contact):

Holger Schoer: Holger.Schoer@all4labels.com

Manuel Aubele: Manuel.Aubele@all4labels.com

