




产品问题反馈 Product Feedback



»» 项目编号-Project NO. : UN20177







Before-改前



After-改后



From UNION (Author: Erik)

From



Ok/Not

Reply time

如图, 孔每边加大15mm
Can we make Hole length longer by 15mm on both sides ?



Before-改前



After-改后


From UNION (Author: Erik)

From


Ok/Not

Reply time

如图，筋位改变
Can we make change on rib design



Before-改前



After-改后



From UNION (Author: Erik)

From



Ok/Not

Reply time

如图，类似的孔，斜度加大到10度
Can we make hole angle to 10 degree



Before-改前



After-改后



From UNION (Author: Erik)

From

Ok/Not

Reply time

如图4个形状头部缩小单边0.2mm方便脱模
Can we reduce by 0.2mm on every side, it will be easier for mold ejection



这张面加了斜度，方便斜顶脱模

| From UNION (Author: Erik) | From | Ok/Not | Reply time |
|---|------|--------|------------|
| Can we add angle on lifter, it will be easier for mold ejection | | | |

Thank You For Reading !
感谢您的阅读！

