






▣ Maintenance judgment standard in order to reduce NTF claims of stabilizer link

Item	0 step (normal)	1 step (normal)	2 step (exchange target)		
Symptom	 Unrestored ball stud	 Partly restored ball stud	 Complete restoration of ball stud	 Complete restoration of ball stud	 Complete restoration of ball stud
Free play	0.075 mm (OK)	0.113 mm (OK)	0.219 mm (OK)	0.440 mm (NG)	0.516 mm (NG)
Abnormal size in real car	No occurrence	No occurrence	No occurrence	Abnormal noise occur	Abnormal noise occur