






## ▣ Maintenance judgment standard in order to reduce NTF claims of stabilizer link

Item	0 step (normal)	1 step (normal)	2 step (exchange target)		
Symptom	 <p data-bbox="285 711 542 739">Unrestored ball stud</p>	 <p data-bbox="623 711 922 739">Partly restored ball stud</p>	 <p data-bbox="980 679 1274 739">Complete restoration of ball stud</p>	 <p data-bbox="1332 679 1626 739">Complete restoration of ball stud</p>	 <p data-bbox="1692 679 1987 739">Complete restoration of ball stud</p>
Free play	0.075 mm (OK)	0.113 mm (OK)	0.219 mm (OK)	0.440 mm (NG)	0.516 mm (NG)
Abnormal size in real car	No occurrence	No occurrence	No occurrence	Abnormal noise occur	Abnormal noise occur