

Basidigital bone fracture

Accident Date 29.01.2020

COMPANY JSC 'NIPIGAS'

Accident location: AGPP, Sub-Project P2, Non-Licensed Units, section 1-110

WHAT HAPPENED?

At 03:00 AM at section 1-110, night shift foreman of AK 'Yamata' (s/c by CPECC), struck his left hand at the process pipe while in the course of works using adjustable wrench. On January 30, 2021 at 08:10 AM, the employee sought medical care in the medical aid station at TCF AK Yamata where the medical staff examined and provided medical assistance. The employee was referred to GBUZ of Svobodny to confirm the diagnosis.

ACTUAL CONSEQUENCES

Closed fracture of 2nd basidigital bone.

WHY DID IT HAPPEN?

1. Breacj of operational process; the employee used construction hammer when tightening the bolts (hit the wrench).
2. Usage of unserviceable tool, when hitting the hammer head fell out from the hand lever and hit the employee's hand.

WHAT CAN YOU DO?

1. Familiarise Contractor and Subcontractors' employees with the circumstances that caused this accident, safety time-outs conducted.
2. Do not breach the operational process;
3. Use serviceable tool when working.

